

HIGH PRESSURE AIR SYSTEM CONTAMINATION

A large amount of desiccant has leaked into the MSFC high pressure air system from the new air compressor facility. Spot checks have found desiccant in far areas of the distribution piping. Until this problem can be corrected, **this system shall not be used for breathing air**. The Industrial Safety Office contact for question or concerns is Dennis Davis. His telephone number is 544-8628.